

Summary of Study Report in Pictures:

Name of PIA		MINAR IRRIGATION [JALSANDHARAN]					Department	JALSANDHARAN	Block	KARANJA
S. n.	Date of Visit	Village	Name of Work	Gut No.	Estimated Cost	Actual Cost	Overall quality	Observations	Recommendation	Photo of observe work/structure
1	21/11/2017	LOHARA	CNB 1	-	11.95	8.59	SATISFACTORY	DRESSING NOT PROPER	REQUIRED DISPLAY BOARD	
2	21/11/2017	LOHARA	CNB 2		11.92	7	GOOD	IN FUTURE CREATE LIKAGE BECAUSE MAINTANANCE IS REQUIRED	NA	
3	21/11/2017	LOHARA	CNB 3		11.55	7	GOOD	DRESSING PROPERLY	NA	
4	21/11/2017	LOHARA	NALA KHOLIKARAN DOHA		2.95	2.88	SATISFACTORY	BIRM NOT FOUND, DRESSING NOT PROPERLY	NA	
5	21/11/2017	BHILKHEDA	CNB 1		13.42	10	GOOD	NA	NA	
6	21/11/2017	BHILKHEDA	CNB 2		14.4	9.64	GOOD	NA	NA	
7	21/11/2017	BHILKHEDA	CNB 3		11.72	9.84	GOOD	WORK COMPLETED BY MEASUREMENT	MAINTANANCE REQUIRED	
8	21/11/2017	VILEGAON	CNB 1		12.1	9.3	SATISFACTORY	NA	NA	
9	21/11/2017	VILEGAON	CNB 2		10.75	9.03	GOOD	NA	NA	

10	21/11/2017	VILEGAON	CNB 3		10.84	8.98	GOOD	INCREASES GROUND WATER LEVEL	NA	
11	21/11/2017	VILEGAON	NALA KHOLIKARAN DOHA		2.99	2.87	SATISFACTORY	BIRM NOT FOUND, DRESSING NOT PROPERLY	NA	
12	21/11/2017	KHERDA BU.	CNB 1		13.31	11.31	GOOD	NA	NA	
13	21/11/2017	KHERDA BU.	CNB 2		12.37	10.51	GOOD	DRESSING PROPERLY, STRUCTURE COMPLETED BY MEASUREMENT	NA	
14	21/11/2017	KHERDA BU.	CNB 3		11.53	10.08	GOOD	NA	NA	
15	21/11/2017	KHERDA BU.	NALA KHOLIKARAN DOHA		2.95	2.85	SATISFACTORY	IN FUTURE CREATE SPLIT PROBLEM	NA	
16	21/11/2017	BELMANDAL	CNB 1		12.16	7.7	GOOD	NA	NA	
17	21/11/2017	BELMANDAL	CNB 2		11.67	7.07	GOOD	NA	NA	
18	21/11/2017	BELMANDAL	CNB 3		11.45	7.08	GOOD	NA	NA	
19	21/11/2017	BELMANDAL	CNB 4		11.22	7.07	GOOD	INCREASES GROUND WATER LEVEL, FORMERS LIFT WATER FOR IRRIGATION	NA	
20	21/11/2017	SUKALI	CNB 1		11.11	8.85	GOOD	NA	NA	

21	21/11/2017	SUKALI	CNB 2		11.39	8.25	GOOD	NA	NA	
22	21/11/2017	SUKALI	CNB 3		11.17	8.25	GOOD	NA	NA	
23	21/11/2017	SUKALI	CNB 4		12.29	8.33	GOOD	DRESSING PROPERLY, STRUCTURE COMPLETED BY MEASUREMENT	NA	
24	21/11/2017	SUKALI	CNB 5		12.27	7.94	GOOD	DRESSING PROPERLY, STRUCTURE COMPLETED BY MEASUREMENT	NA	
25	21/11/2017	SUKALI	CNB 6		12.03	7.6	GOOD	NA	NA	
26	21/11/2017	SUKALI	CNB 7		10.12	7.94	SATISFACTORY	NA	NA	
27	21/11/2017	SUKALI	CNB 8		4.73	4.15	GOOD	DRESSING PROPERLY, STRUCTURE COMPLETED BY MEASUREMENT	NA	
28	21/11/2017	SUKALI	CNB 9		7.36	4.05	GOOD	DRESSING PROPERLY, STRUCTURE COMPLETED BY MEASUREMENT	NA	
29	21/11/2017	SOHAL	CNB 1		14.09	9.01	SATISFACTORY	DRESSING NOT PROPER, IN FUTURE CREAT LIKAGE PROBLEMS	NA	
30	21/11/2017	SOHAL	CNB 2		11.4	9.01	GOOD	NA	NA	
31	21/11/2017	SOHAL	CNB 3		10.96	9.01	GOOD	NA	NA	

32	21/11/2017	SOHAL	CNB 4		10.67	9.01	GOOD	NA	NA	
33	21/11/2017	SOHAL	CNB 5		11.68	9.01	GOOD	NA	NA	
34	21/11/2017	SOHAL	NALA KHOLIKARAN		2.99	2.88	SATISFACTORY	BIRM NOT FOUND, DRESSING NOT PROPERLY	NA	
35	21/11/2017	DADGAON	CNB 1		21.63	9.1	GOOD	NA	NA	
36	21/11/2017	DADGAON	CNB 2		10.39	9.02	GOOD	NA	NA	
37	21/11/2017	DADGAON	CNB 3		10.14	8.97	GOOD	NA	NA	
38	21/11/2017	DADGAON	CNB 4		2.99	1.66	GOOD	NA	NA	
39	21/11/2017	WALHAI	NALA KHOLIKARAN DOHA		2.95	2.81	GOOD	NA	NA	
40	21/11/2017	WALHAI	NALA KHOLIKARAN DOHA		2.95	2.88	GOOD	NA	NA	
41	21/11/2017	KOLI	NALA KHOLIKARAN DOHA		2.95	2.77	GOOD	NA	NA	

42	21/11/2017	SHIVNAGAR	NAALA KHOLIKA RAN DOHA		2.95	2.82	GOOD	NA	NA	
43	21/11/2017	TULJAPUR	NALA KHOLIKA RAN DOHA		2.95	2.78	GOOD	NA	NA	
44	21/11/2017	TULJAPUR	NALA KHOLIKA RAN DOHA		2.91	2.81	GOOD	NA	NA	
45	21/11/2017	DONGARGAON	NALA KHOLIKA RAN DOHA		9.20	7.84	GOOD	NA	NA	
46	22/11/2017	YAWRDI	CNB 1		11.81	11.8	GOOD	NA	NA	
47	22/11/2017	YAWRDI	CNB 2		12.14	12.1	GOOD	NA	NA	
48	22/11/2017	YAWRDI	NALA KHOLIKA RAN DOHA		3	2.82	GOOD	NA	NA	
49	22/11/2017	YAWRDI	NALA KHOLIKA RAN DOHA		6.94	5.87	SATISFACTORY	BIRM NOT FOUND, DRESSING NOT PROPERLY	NA	
50	22/11/2017	MURAMBI	CNB 1		11.4	11.35	GOOD	USEFULL OF THE FORMERS	NA	
51	22/11/2017	MURAMBI	CNB 2		11.04	11	GOOD	NA	NA	

52	22/11/2017	MURAMBI	CNB 3		14.03	14	GOOD	NA	NA	
53	22/11/2017	UMBRDA	CNB 1		14.7	11.43	SATISFACTORY	DRESSING NOT PROPER	NA	
54	22/11/2017	UMBRDA	CNB 2		11.47	11.43	GOOD	NA	NA	
55	22/11/2017	UMBRDA	CNB 3		9.88	8.8	GOOD	NA	NA	
56	22/11/2017	UMBRDA	NALA KHOLIKARAN DOHA		3.79	3.05	GOOD	NA	NA	
57	22/11/2017	SHAHAPUR	NALA KHOLIKARAN DOHA		9.97	9.29	GOOD	USEFULL OF THE FORMERS, WATER LIFTED BY FORMERS	NA	
58	22/11/2017	WAI	NALA KHOLIKARAN DOHA		7.07	6.77	GOOD	NA	NA	
59	22/11/2017	BELKHED	CNB 1		10.07	9.47	GOOD	NA	NA	
60	22/11/2017	BELKHED	CNB 2		10.16	9.47	GOOD	USEFULL OF THE FORMERS	NA	
61	22/11/2017	BELKHED	CNB 3		9.93	9	GOOD	NA	NA	

62	22/11/2017	KAJLESHWAR	CNB 1		95.88	8.4	GOOD	NA	NA	
63	22/11/2017	KAJLESHWAR	CNB 2		9.58	8.3	GOOD	USEFULL OF THE FORMERS	NA	
64	22/11/2017	KAJLESHWAR	CNB 3		9.26	8.9	GOOD	NA	NA	
65	22/11/2017	DHOTRA	CNB 1		10.48	8.87	GOOD	NA	NA	
66	22/11/2017	DHOTRA	CNB 2		9.64	8.87	GOOD	NA	NA	
67	22/11/2017	DHOTRA	CNB 3		9.99	8.87	SATISFACTORY	CREATE LIKAGE PROBLEM WITHOUT MAINTANCE	HAND OVER TO USER GROUP	
68	22/11/2017	DHOTRA	NALA KHOLIKARAN DOHA		9.47	8.81	SATISFACTORY	DRESSING NOT PROPER	NA	
69	22/11/2017	KARLI	CNB 1		11.24	11.2	GOOD	NA	NA	
70	22/11/2017	KARLI	CNB 2		11.04	11	GOOD	NA	NA	
71	22/11/2017	KARLI	CNB 3		11.32	11.3	GOOD	NA	NA	

72	22/11/2017	KARLI	NALA KHOLIKA RAN DOHA		3	2.82	GOOD	NA	NA	
73	22/11/2017	KARLI	NALA KHOLIKA RAN DOHA		7	4.62	SATISFACTO RY	DRESSING NOT PROPER	NA	
74	22/11/2017	PASARNI	CNB 1		11.16	9.79	GOOD	NA	NA	
75	22/11/2017	PASARNI	CNB 2		12.09	9.8	GOOD	NA	NA	
76	22/11/2017	PASARNI	CNB 3		11.76	9.78	GOOD	INCREASE WATER LEVEL	NA	
					794.6	577.22				

Summary of Study Report in Pictures:

Name of PIA		FOREST					Department	FOREST	Block	KARANJA
S. n.	Date of Visit	Village	Name of Work	Gut No.	Estimated Cost	Actual Cost	Overall quality	Observations	Recommendation	Photo of observe work/structure
1	21/11/2017	WADHAVI	C.C.T.	C-40 A	1.47	0.89	GOOD	CCT MEASURED BY HYDROMETER	NA	
2	21/11/2017	WADHAVI	C.C.T.	C-40 B	1.47	0.9	GOOD	NA	NA	
3	21/11/2017	WADHAVI	FOREST POND	C-40	1.48	0.88	POOR	DRESSING NOT PROPER, INLET AND OUTLET IS NOT PROPER	NA	
4	21/11/2017	BELMANDAL	C.C.T.	B-203	1.47	0.91	GOOD	NA	NA	
5	21/11/2017	WALHAI	C.C.T.	C-110	1.77	0.94	GOOD	NA	NA	
6	21/11/2017	DADGAON	FOREST POND	C-124	1.59	0.99	SATISFACTORY	DRESSING NOT PROPER, INLET AND OUTLET IS NOT PROPER	NA	
7	21/11/2017	DADGAON	DIP-C.C.T.	C-124	1.47	0.89	GOOD	NA	NA	
8	21/11/2017	INUHA	DIP-C.C.T.	C-115	1.47	0.9	GOOD	NA	NA	
9	21/11/2017	INUHA	FOREST POND	C-115	1.59	1.04	POOR	WORK UNCOMPLETE BY HARD ROCK	NA	

10	21/11/2017	RAPERI	M.N.B	C-114	7.15	6.08	GOOD	THIS STRUCTURE USEFULL OF SAVING WATER CONSERVATION	NA	
					20.93	12.63				

Summary of Study Report in Pictures:

Name of PIA		LAGUSINCHAN UP VIBHAG KARNJA					Department	LUVK	Block	KARNJA
S. n.	Date of Visit	Village	Name of Work	Gut No.	Estimated Cost	Actual Cost	Overall quality	Observations	Recommendation	Photo of observe work/structure
1	20/11/2017	KAMARGAON	CNB & DND		11.98	10.48	Good	1) Increases ground water level. 2) Pumps were installed on nala for gives protective irrigation	formers should remove silt every year	
2	20/11/2017	KAMARGAON	CNB & DND		8.24	7.24	GOOD	DRESSING PROPERLY, WORK COMPLETED BY MEASUREMENT	NA	
3	20/11/2017	KAMARGAON	CNB & DND		8.49	7.53	GOOD	NA	NA	
4	20/11/2017	KAMARGAON	CNB & DND BANDHRA REPAIRING		10.26	9.88	SATISFACTORY	NA	NA	
5	20/11/2017	DUGHORA	CNB & DND		7.57	4.73	SATISFACTORY	DRESSING NOT PROPER	NA	
6	20/11/2017	INJHA	CNB & DND		11.45	10.09	GOOD	NA	NA	
7	20/11/2017	INJHA	CNB & DND		11.93	11.01	GOOD	NA	NA	

8	20/11/2017	DONAD	CNB & DND		3.3	3.29	GOOD	NA	NA	
9	20/11/2017	DONAD	CNB & DND		9.26	7.92	GOOD	NA	NA	
10	20/11/2017	DONAD	CNB & DND		7.26	7	SATISFACTORY	DRESSING NOT PROPER	NA	
11	20/11/2017	MUNGUTPUR	CNB & DND		9.64	8.97	GOOD	NA	NA	
12	20/11/2017	JAYPUR	CNB & DND		6.24	4.64	SATISFACTORY	NA	HANDOVER TO USER GROUP	
13	20/11/2017	JAYPUR	CNB & DND		11.93	7.41	GOOD	NA	NA	
14	20/11/2017	LADEGAON	CNB		7.5	6.5	GOOD	NA	NA	
15	20/11/2017	LADEGAON	CNB		7.32	7.17	SATISFACTORY	MAINTANANCE REQUIRED	NA	

16	20/11/2017	LADEGAON	CNB		7.76	6.16	GOOD	NA	HANDOVER TO USER GROUP	
17	20/11/2017	MANBHA	CNB & DND		6.6	5.7	GOOD	NA	NA	
18	20/11/2017	MANBHA	CNB & DND		12.17	11.19	SATISFACTORY	BIRM NOT FOUND, DRESSNG NOT PROPERLY	NA	
19	20/11/2017	MANBHA	CNB & DND		7.07	6.8	GOOD	NA	NA	
20	20/11/2017	MANBHA	CNB & DND		14.14	13.72	SATISFACTORY	DRESSING NOT PROPER	NA	
21	21/11/2017	DIGHI	CNB & DND		5.68	4.44	GOOD	NA	NA	
22	21/11/2017	DIGHI	PAZAR TALAV DURUSTI		7.5	2.7	GOOD	NA	NA	
23	21/11/2017	DADGAON	CNB & DND		21.14	16.76	Good	1) Increases ground water level. 2) Pumps were installed on nala for gives protective irrigation	formers should remove silt every year	

24	21/11/2017	DONGARGAON	CNB & DND		14.11	7.06	GOOD	NA	NA	
25	21/11/2017	HIVRALAHE	CNB & DND		20.2	16.01	GOOD	NA	NA	
26	21/11/2017	KHERDA KARANJA	CNB & DND		25.47	21.26	GOOD	NA	NA	
27	21/11/2017	BHAMDEVI	SHET TALA		7.25	6.14	Good	1) Increases ground water level. 2) Pumps were installed on nala for gives protective irrigation	formers should remove silt every year	
28	21/11/2017	BHAMDEVI	SHET TALA		6.5	5.5	GOOD	NA	NA	
29	21/11/2017	PASARNI	CNB & DND		24.2	15.21	Good	1) Increases ground water level. 2) Pumps were installed on nala for gives protective irrigation	formers should remove silt every year	
30	21/11/2017	WAI	TALAV DURUSTI		2.16	2.16	GOOD	NA	NA	
31	21/11/2017	WAI	TALAV DURUSTI		1.9	1.9	GOOD	NA	NA	

32	21/11/2017	UKARDA	KO. PA. BANDHARA		3.27	1.7	SATISFACTORY	STRUCTURE IS DAMAGE WITHOUT MAINTANANCE	NA	
33	21/11/2017	TULJAPUR	TALAV DURUSTI		5.77	4.16	GOOD	NA	HANDOVER TO USER GROUP	
34	21/11/2017	POHA	CNB & DND		15.37	12.2	GOOD	INCREASE WATER LEVEL	NA	
35	21/11/2017	KINKHED	TALAV DURUSTI		6.47	5.79	GOOD	NA	formers should remove silt every year	
36	21/11/2017	KINKHED	TALAV DURUSTI		4.37	3.31	GOOD	NA	NA	
37	21/11/2017	KINKHED	KO. PA. BANDHARA		5.12	1.5	GOOD	NA	NA	
38	21/11/2017	SOHAL	TALAV DURUSTI		4.55	4.51	SATISFACTORY	NA	NA	
39	21/11/2017	LOHGAON	KO. PA. BANDHARA		4.17	2.38	GOOD	NA	NA	
40	21/11/2017	WALAI	KO. PA. BANDHARA		5.75	3.1	SATISFACTORY	REQUIRMENT OF REPAIRE	NA	
41	21/11/2017	BELMANDAL	KO. PA. BANDHARA		5.24	1.51	SATISFACTORY	NA	formers should remove silt every year	

42	21/11/2017	BELMANDAL	KO. PA. BANDHARA		4.68	0.65	GOOD	NA	NA	
43	21/11/2017	BELMANDAL	TALAV DURUSTI		3.03	2.46	GOOD	INCREASE WATER LEVEL	NA	
44	21/11/2017	DHANAJ BU.	CNB & DND		15.77	14.24	GOOD	NA	NA	
45	21/11/2017	DHANAJ BU.	CNB & DND		5.25	4.73	GOOD	INCREASE WATER LEVEL, FORMER LIFT WATER FOR IRRIGATION	NA	
46	21/11/2017	YAWARDI	CNB & DND		11.36	8.07	SATISFACTORY	DRESSING NOT PROPER	REQUIRED DISPLAY BOARD	
47	21/11/2017	SHIVAN BU.	CNB & DND		17.3	14.13	GOOD	NA	NA	
48	21/11/2017	BAPTI KUPTI	CNB & DND		7.73	4.4	GOOD	NA	NA	
49	21/11/2017	UMBARDA BAJAR	CNB & DND		17.26	13.82	SATISFACTORY	DRESSING NOT PROPER, BIRM NOT FOUND	NA	
50	21/11/2017	KAJLESHWAR	CNB & DND		3	2.95	Good	1) Increases ground water level. 2) Pumps were installed on nala for gives protective irrigation	formers should remove silt every year	

51	21/11/2017	BAGAPUR	CNB & DND		8.33	8.33	Good	1) Increases ground water level. 2) Pumps were installed on nala for gives protective irrigation	formers should remove silt every year	
52	21/11/2017	BAGAPUR	CNB & DND		11.69	7.9	GOOD	NA	NA	
53	21/11/2017	BAGAPUR	TALAV DURUSTI		8.85	5.99	GOOD	NA	NA	
					490.55	384.4				

Name of PIA		GRAMIN PANI PURWATHA UP VIBHAG					Department	GPPUV	Block	KARANJA
S. n.	Date of Visit	Village	Name of Work	Gut No.	Estimated Cost	Actual Cost	Overall quality	Observations	Recommendation	Photo of observe work/structure
1	23/11/2017	DADGAON	BHUMIG AT BHANDARA V TRENCH PIT		2.93	2.87	SATISFACTORY	WELL RECHARGE	NA	
2	23/11/2017	POHA	BHUMIG AT BHANDARA V TRENCH PIT		2.91	2.82	SATISFACTORY	NA	NA	
3	23/11/2017	BELMANDAL	BHUMIG AT BHANDARA V TRENCH PIT		2.94	2.87	SATISFACTORY	WELL RECHARGE	NA	
4	23/11/2017	HIWRA LAHE	BHUMIG AT BHANDARA V TRENCH PIT		2.96	2.46	SATISFACTORY	NA	NA	
5	23/11/2017	BHAMDEVI	BHUMIG AT BHANDARA V TRENCH PIT		2.9	2.84	SATISFACTORY	WELL RECHARGE	NA	
6	23/11/2017	PIMPRI MODKU	BHUMIG AT BHANDARA V TRENCH PIT		2.93	2.86	SATISFACTORY	NA	NA	
7	23/11/2017	BORGAON	BHUMIG AT BHANDARA V TRENCH PIT		2.88	2.82	SATISFACTORY	INCREASE GROUND WATER LEVEL	NA	
8	23/11/2017	WILEGAON	BHUMIG AT BHANDARA V TRENCH PIT		2.53	2.46	SATISFACTORY	NA	NA	
9	23/11/2017	SOHOL	BHUMIG AT BHANDARA V TRENCH PIT		2.94	2.87	SATISFACTORY	NA	NA	
10	23/11/2017	KOLI	BHUMIG AT BHANDARA V TRENCH PIT		2.87	2.81	SATISFACTORY	WELL RECHARGE	NA	

11	23/11/2017	WADHAVI	BHUMIG AT BHANDA RA V TRENCH PIT		2.99	2.91	SATISFACTO RY	NA	NA	
12	24/11/2017	MALEGAON	BHUMIG AT BHANDA RA V TRENCH PIT		0.95	0.92	SATISFACTO RY	NA	NA	
13	24/11/2017	DHOMA JAHANGIR	BHUMIG AT BHANDA RA V TRENCH PIT		1.12	0.94	SATISFACTO RY	NA	NA	
14	24/11/2017	TAKLI KHURD	BHUMIG AT BHANDA RA V TRENCH PIT		0.55	0.53	SATISFACTO RY	NA	NA	
15	24/11/2017	SHIWAN BU.	BHUMIG AT BHANDA RA V TRENCH PIT		2.27	2.22	SATISFACTO RY	NA	NA	
16	24/11/2017	KAJLESHWAR	BHUMIG AT BHANDA RA V TRENCH PIT		1.75	1.72	SATISFACTO RY	NA	NA	
17	24/11/2017	TANDALI	BHUMIG AT BHANDA RA V TRENCH PIT		2.03	1.98	SATISFACTO RY	DRESSING NOTPROPER	NA	
18	24/11/2017	PIMPRI WARGHAT	BHUMIG AT BHANDA RA V TRENCH PIT		1.47	1.43	SATISFACTO RY	NA	NA	
19	24/11/2017	MURAMBI	BHUMIG AT BHANDA RA V TRENCH PIT		1.36	1.32	SATISFACTO RY	NA	NA	
20	24/11/2017	GAYBAL	BHUMIG AT BHANDA RA V TRENCH PIT		1.46	1.43	SATISFACTO RY	NA	NA	
21	24/11/2017	DEVCHANDI	BHUMIG AT BHANDA RA V TRENCH PIT		1.75	1.71	SATISFACTO RY	NA	NA	

					46.49	44.79				
--	--	--	--	--	-------	-------	--	--	--	--